

MERITOR WABCO

Technical Bulletin

Brake Fluid Replacement Requirement

Fluid Requirement

This bulletin supplements the information contained in Meritor WABCO Maintenance Manual, MM-0401: Meritor WABCO Hydraulic Power Brake (HPB) system for the regular maintenance of the Meritor WABCO HPB System. For the proper functioning of the system, seals and components, Meritor WABCO recommends replacing brake fluid every TWO (2) years on all vehicles equipped with Meritor WABCO HPB system. This is done to minimize exposure to contaminated brake fluid. To replace the brake fluid, please follow the instructions indicated under the title "Changing Hydraulic Brake Fluid" under Section 5 of MM-0401.

NOTE: Please keep this document with MM-0401 for vehicle users to refer to this document for regular maintenance.

NOTE: While changing the brake fluid according to instructions under Section 5 of MM-0401, please read and observe all Warning and Caution hazard alert messages published onwards from Page 52 of MM-0401 under Section 5, apart from those published below.

⚠ WARNING

Never reuse hydraulic brake fluid that has been removed from a vehicle. Hydraulic brake fluid that has been removed can be contaminated and can cause damage, loss of braking and serious personal injury. Always discard hydraulic brake fluid in accordance with applicable environmental requirements.

Use DOT 3 or DOT 4 hydraulic brake fluid. Refer to the vehicle specification sheet to determine which fluid to use. Do not use or mix different types of hydraulic brake fluid. The incorrect hydraulic brake fluid will damage the rubber parts of the brake caliper and can cause damage, loss of braking and serious personal injury.

MERITOR WABCO

Meritor WABCO Vehicle Control Systems
2135 West Maple Rd
Troy, MI 48084-7121 USA
866-OnTrac1 (668-7221)
meritorwabco.com

Information contained in this publication was in effect at the time the publication was approved for printing and is subject to change without notice or liability. Meritor WABCO reserves the right to revise the information presented or to discontinue the production of parts described at any time.

Copyright 2014
Meritor, Inc.
All Rights Reserved

Printed in USA

TP-1367
Issued 03-14
(16579)